Step-by-Step B3 Compliance Demonstration Monthly Allowable Organic HAP Applied '63.3370(d)

Overview: This approach allows a facility to average all coatings and use a combination of MACT limits. The approach recognizes that the organic HAP mass fraction limit is less stringent for coatings applied at less than 20% solids whereas the organic HAP to solids mass fraction limit is less stringent for coatings applied at greater than 20% solids.

In this approach, a facility needs to:

- 1. Identify all coatings and additives used in process.
- 2. Gather "NESHAP quality" data for each coating material applied.

MACT limits

Existing Sources

 $H_L \le 0.04 \text{ kg HAP/kg coating}$

 $H_S \le 0.20 \text{ kg HAP/kg solids}$

New Sources

 $H_L \le 0.016 \text{ kg HAP/kg coating}$

 $H_S \le 0.08 \text{ kg HAP/kg solids}$

See separate listing of all variables

- 3. Calculate the total organic HAP applied in a month. (Note: Total organic HAP applied recognizes allowance for volatile retained on the web.)
- 4. Calculate the total allowable organic HAP for the month.
- 5. Demonstrate that the total organic HAP applied is less than the calculated allowable.
- 6. Maintain monitoring and other compliance records.

| 1. Identify all coatings and additives | | |
|---|---|-------------------------|
| 1. Identify all coatings and additives used in process. | | 63.3370(l)(1) |
| 2. Determine the as-purchased coating solids content for each coating | | ' 63.3370(1)(2) |
| material (' 63.3360(d)(1)) using one | e of the following: | |
| Method 24 | | |
| Determine the VOC as a mass fraction of non-aqueous volatile | | §63.3360(d)(2) and App. |
| matter and substitute for organic HAP content. | | A of Part 60. |
| Calculate solids content from measured volatile content. | | |
| OR | | |
| Formulation data | | |
| Provided by the manufacturer of the material | | §63.3360(d)(3) |
| Method 311 data takes precedence when available | | |
| Formulation data must meet the criteria for quantifying organic | | |
| HAPs as defined (above) under Method 311. | | |
| 3. Calculate the total organic HAP ap | | |
| • Use Equation 6 (63.3370(d)) | Per 40 CFR 63.3360(g), in order to use the | §63.3370(d) |
| to calculate the total organic | volatile matter retained on web allowance, | |
| HAP applied in a month | one must either use volatile organic matter as a surrogate for HAP content in the | |
| | coating or determine the mass of organic | |
| | HAP retained on the web for use as M $_{\mbox{\scriptsize vret}}$ | |
| | | |

FINAL: April 30, 2005 Subpart JJJJ, Step by Step Compliance Demonstration

Step-by-Step B3 Compliance Demonstration Monthly Allowable Organic HAP Applied '63.3370(d)

| Detailed Approach | | Citation |
|--|---|--|
| 4. | Determine the as-purchased mass fraction of coating materials | 63.3370(1)(3) |
| | which were applied at ≥ 20 % (mass) on an as-applied basis. | |
| 5. | Determine the mass of each solvent, diluent, thinner, or reducer | '63.3370(l)(4) |
| | added to coating materials applied at $< 20 \%$ (mass) coating solids | |
| | content on an as-applied basis each month. | |
| 6. | Calculate the total allowable organic HAP for the month using | '63.3370(l)(5) |
| | equations 13a or 13b of 40 CFR 63.3370. | |
| | • Use Equation 13a to calculate the total organic HAP allowable for a | |
| | month for existing affected facilities | |
| | II E (121 CAO GED (2 2270) 1 1 4 41 4 4 1 1 1 | |
| | • Use Equation 13b of 40 CFR 63.3370 to calculate the total organic | |
| | HAP allowable for a month for new affected facilities | |
| 7. Demonstrate that the total organic HAP applied is less than the | | The method requires that each |
| | calculated allowable. | individual coating as-applied |
| | • The total organic HAP applied in a month, H _m , is calculated using | (including all additions) needs to |
| | equation 6. | be tracked separately and that for each coating a determination must |
| | • The total organic HAP allowed in a month, H _a , is calculated using | be made as to solids content |
| | equation 13a or 13b. | (above or below 20%) |
| | • You are in compliance if $H_m < H_a$. | |
| | • H _m and H _a need to be calculated based on all coating constituents | |
| 0 | applied in a month. | |
| 8. | Maintain compliance records. | 862 2410(a)(1)(iii) |
| | Maintain records of organic HAP content data. Maintain records of valetile metter and parting solids content data. | §63.3410(a)(1)(iii) '63.3410(a)(1)(iv) |
| | Maintain records of volatile matter and coating solids content data Maintain records of material years arganic IIAP was a valetile. | \$63.3410(a)(1)(vi) |
| | Maintain records of material usage, organic HAP usage, volatile | 803.3410(a)(1)(v1) |
| | matter usage, and coating solids usage and compliance | |
| | demonstrations. | |

Credits: This document was made possible through the efforts of the POWC Implementation Tool Development Partnership effort, an effort to bring together the regulated and regulatory community. It was through a group effort that this document was developed. The logo of the partner who was the lead for this tool is listed first below. To see a description of our partners or to get more information about the partnership effort, see http://wwww.epa.gov/ttn/atw/powc/powcpg.html



FINAL: April 30, 2005

Subsect HH. Step by Step Compliance Demonstration